

Project open house meeting

City project number:


10535 – Wilson Creek

Project website:


www.mankatoconstruction.com

Important information

1. Please sign in



2. Take a packet & return comment card card



Introductions


- Michael McCarty Project Engineer 507-387-8643 mmccarty@mankatomn.gov
- Bridget Anderson– Project Designer 507-720-4472
 ETI@mankatomn.gov

Project success

Our plan for project success begins now. When citizens and city staff work together, we can build a relationship to take this project successfully to completion through suggestions, assistance and good communication.


Why project work is needed


- ➤ Many calls for service for
 - Vegetation Management
 - > Bank and Channel Erosion
- ➤ A comprehensive plan is needed to provide cost effective lasting solutions





7


- Nearly 3000 acres of drainage pass through Wilson Creek
- Originally a natural stream, modified to become a County Ditch
- Straightened and moved with the paving and extension of Hoffman Road to TH 22.
- Various development aspects within water sheds
 - East High School area
 - Basset Drive area
 - Undeveloped areas












Study Area

- Zone 1 Hoffman Rd. Ditch section
- Zone 2 Narrow creek with young vegetation
- Zone 3 Downstream of two 60-inch storm pipes – wider straight channel
- Zone 4a: South of Crystal Lane relatively straight, limited bank erosion.
- Zone 4b: Most pronounced bank erosion, tight meanders, high banks.
- Zone 4c Meanders with short banks, sediment bars
- Zone 5 Hosanna Ave to Hwy 83



Zone 1

- Zone 1 Hoffman Rd. Ditch section
- Zone 2 Narrow creek with young vegetation
- Zone 3 Downstream of two 60-inch storm pipes – wider straight channel
- Zone 4a: South of Crystal Lane relatively straight, limited bank erosion.
- Zone 4b: Most pronounced bank erosion, tight meanders, high banks.
- Zone 4c Meanders with short banks, sediment bars
- Zone 5 Hosanna Ave to Hwy 83

Zone 1: Creek = Ditch on south side of Hoffmann Rd:

a) General view (note steep sides)

- b) Closeup typical section
- c) Culvert at Hosanna Dr. receiving major storm sewer inflow (60-in pipe from north)





Zone 1 CONTINUED Creek = Ditch on south side of Hoffmann Rd: a) Potential for side sloughing b) Closeup








Zone 1: Highway 22 to west of Hosanna Avenue
Wilson Creek is being utilized as a ditch on south side of Hoffman Road.
Vegetation adjacent to the ditch is mostly non-native species like brome and Canada goldenrod. Areas of invasive species such as vetch (lower left) are present.





Wilson Creek – Zone 1

- Identified needs:
 - Potential slope failures and sloughing
 - Relatively steep banks, near traveled way
 - High velocities
- Potential improvement
 - Continued vegetation management
 - Flow reduction
 - Possible pipe installation from TH 22 Hosanna or Thomas Drive




Zone 2

- Zone 1 Hoffman Rd. Ditch section
- Zone 2 Narrow creek with young vegetation
- Zone 3 Downstream of two 60-inch storm pipes – wider straight channel
- Zone 4a: South of Crystal Lane relatively straight, limited bank erosion.
- Zone 4b: Most pronounced bank erosion, tight meanders, high banks.
- Zone 4c Meanders with short banks, sediment bars
- Zone 5 Hosanna Ave to Hwy 83

Zone 2: Creek flows southwest through young trees: Typical views – note significant widening due to capture of storm sewer discharge.








Wilson Creek – Zone 2

- Identified needs:
 - Potential slope failures and sloughing
 - High velocities
 - Invasive and undesirable vegetation
- Potential improvement
 - Continued vegetation management
 - Flow reduction

Zone 2: Wooded Area of Wilson Creek between Hoffman Road and storm water outlets. Creek is narrower and deeper when compared to downstream of outlets. Creek was likely "straightened" in the past. Vegetation is comprised of early successional tree species and native shrubs. Buckthorn is present, but in low concentrations.







Zone 3

- Zone 1 Hoffman Rd. Ditch section
- Zone 2 Narrow creek with young vegetation
- Zone 3 Downstream of two 60-inch storm pipes – wider straight channel
- Zone 4a: South of Crystal Lane relatively straight, limited bank erosion.
- Zone 4b: Most pronounced bank erosion, tight meanders, high banks.
- Zone 4c Meanders with short banks, sediment bars
- Zone 5 Hosanna Ave to Hwy 83

Zone 3: South of the two 60-inch storm sewer pipes: Views of Storm Sewer Pipes and concrete wing apron: a) looking upstream b) looking downstream

c) oversized corrugated culvert pass.









Zone 3 - CONTINUED: South of storm sewer structures. Creek flows south through more trees.

a) & b) Typical views — note significant widening due to capture of storm sewer discharge. This portion is relatively straight showing little bank erosion c) Corrugated metal pipe





Zone 3: Water control structure/Outlets to Crystal Lane.

Wilson Creek is wider and shallower than above structures. Bank erosion is minimal. Buckthorn is more prevalent (80% coverage) and varies from 6 to 15 tall. Tree canopy is comprised of larger diameter trees. Species is mixture of native maples and less desirable boxelder tree.












Wilson Creek - Zone 3

- Identified needs:
 - High velocities
 - Invasive and undesirable vegetation
- Potential improvement
 - Continued vegetation management
 - Flow reduction



Zone 4

- Zone 1 Hoffman Rd. Ditch section
- Zone 2 Narrow creek with young vegetation
- Zone 3 Downstream of two 60-inch storm pipes – wider straight channel
- Zone 4a: South of Crystal Lane relatively straight, limited bank erosion.
- Zone 4b: Most pronounced bank erosion, tight meanders, high banks.
- Zone 4c Meanders with short banks, sediment bars
- Zone 5 Hosanna Ave to Hwy 83

Zone 4a: South of Crystal Lane – views immediately south of Crystal Lane culvert crossing:

- a) Erosion in the left (east) bank partly contained with rock placement b) close up of soils
- c) Limited on the opposite (right, west) bank and d) further downstream on both sides











Zone 4a (CONTINUED): Typical views (upstream to downstream) - relatively straight channel, mature, native vegetation. Banks 3-4 feet high. Note presence of channel (sediment) bars





Zone 4b: Entering tight meander portion, approx. 0.15 miles south of Crystal Lane





Zone 4b (CONTINUED) - Tight meanders, significant bank erosion, at one location bank failure is near a residential property. Corrugated pipe suggest significant bank migration.





Zone 4b (CONTINUED) – Region of tight meanders and bank erosion spans about 0.3 miles











Zone 4b (CONTINUED) – Further downstream, same tight meanders and bank erosion with more vegetation debris and channel point bars present.










Zone 4c – Further downstream, just north of Hosanna Ave, meanders and mature vegetation but a significant a reduction in bank height and flow rate (possible infiltration)





Zone 4a: Wilson Creek from Crystal Lane to approximately halfway to Hosanna Drive. This section of Wilson Creek is straight, wide, and shallow. Erosion is more prevalent (south of Crystal Lane on east side and banks). Vegetation is great example of "Big Woods" ecosystem. Some buckthorn present, but generally small diameter and light densities.











Zone 4b: Halfway from Crystal Lane to Hosanna Lane.

Wilson Creek begins to meander similar to natural stream. Bank erosion is more prevalent and closer to homes. Buckthorn in higher densities (near culvert at Hosanna Lane). Less desirable tree species of boxelder and cottonwoods present, but many native trees present.











Zone 4b (continued): Additional photos from Zone 4.





Zone 4c: North of Hosanna Lane

Area has downed timber in creek and oxbow. Tree canopy is more open allowing reed canary

grass to become established.












Wilson Creek - Zone 4

- Identified needs:
 - High velocities
 - Invasive and undesirable vegetation
 - Vegetation impeding flow
 - Bank and channel erosion
- Potential improvement
 - Continued vegetation management
 - Remove vegetation from flowage way
 - Prevent fall-in
 - Flow reduction
 - Stabilize bank



Zone 5

- Zone 1 Hoffman Rd. Ditch section
- Zone 2 Narrow creek with young vegetation
- Zone 3 Downstream of two 60-inch storm pipes – wider straight channel
- Zone 4a: South of Crystal Lane relatively straight, limited bank erosion.
- Zone 4b: Most pronounced bank erosion, tight meanders, high banks.
- Zone 4c Meanders with short banks, sediment bars
- Zone 5 Hosanna Ave to Hwy 83

Zone 5 – Between Hosanna Ave and Highway 83 (Stadium Rd) Upstream to Downstream:

- a) sediment pile up just south of Hosanna Ave culvert; b) vegetation debris
- c) a short stretch with boulder walls in left bank; d) upstream of Highway 83











Zone 5: Hosanna Lane to 209th Street (Stadium Road).

Wilson Creek appears to be meandering slightly. Tree vegetation is comprised of less desirable species (boxelder and cottonwoods). Buckthorn is prevalent and more mature.











Wilson Creek - Zone 5

- Identified needs:
 - High velocities
 - Invasive and undesirable vegetation
 - Vegetation impeding flow
 - Bank and channel erosion
 - Backup Flooding
- Potential improvement:
 - Continued vegetation management
 - Remove vegetation from flowage way
 - Prevent fall-in
 - Flow reduction
 - Stabilize bank
 - Culvert replacement CSAH 60

Watershed Improvements

Development will help improve drainage characteristics:

- Regional pond with school development
- CSAH 12 stormwater controls
- Improvements help to control drainage to and from the wetland east of CSAH 12
- Reduce flow through Diamond Creek neighborhood

Benefits:

- Reduce in-channel erosion
- Reduce wood debris in channel
- Reduce calls for service
- Help Mankato Townships and Blue Earth County comply with MS4 permit requirements

Watershed Improvements

Improvements to existing system:

- Increase storage behind Wal-Mart
- Attenuate flows from Hoffman Road/East Main Street
- Stabilize banks

Project schedule

2016

January Informational meeting – Draft recommendations

February Present to council

March Begin Implementation of council's direction

Apply for funding

Preliminary Design and cost Estimates

Neighborhood meeting

Final Design

Special Assessment process

2017 – 2019 (funding dependant)

June Begin construction

The next steps

Informal meetings will be held prior to the project's start to discuss project phases and details of the final design.

Help us help you

- If there is helpful information unique about the neighborhood, please share it with us so it can be incorporated into the plan, or addressed by a city staff member.
- If there are any questions, or suggestions, please let engineering staff know.